Please complete every section daily and give to at ENV Station 001.

Date: 3/30/10 Time: 2:30 P.W. Initials: TRI

Outfall 009/010	Answers	
Substance discharged?	Y / (N) Ja Some St.
-If Yes, Color?) - some Shan In Corner by
-If Yes, Size / Area?	- Annual -	correct by
Vac truck amount recovered		MET bridge
Estimated oil recovered	0	
Length of sorbent boom replaced	0	
Canal Appearance (winds, sheen, etc.)	nw- 20-25 mg	1.
	heavi	V4

Date: 3/10/17

Time: 3:15 p.m Initials: TRE


Answers	
Y / (N)	
, , , ,	
<u></u>	
0	
0	
Nw -70-75 100 01	

heary tour.

Some Sheen outsine Stel webt, inside Soft booms, City oran Claw was contributing to this.

Pit covers must remain on at all times

Date: 3-38-17
Time: //30 An
Initials: wn




Sump Pits	Clean	Oil Sheen & Color	Comments	
70k Room	t to			
6 Turbo Blower		Sump Water Diverted to Ash Pit		
7 Generator		Sump Water Diverted to Ash Pit		
5 Turbo Blower	***************************************	Sump Water Diverted to Ash Pit		
7 Turbo Blower	1/			
2300VAC Room	1			
8 Generator		Sump Water Diverted to Ash Pit		

If oil is found in sump pit contact KM to have the pit cleaned out.

Power House Basement Sump Pump Pit Inspection Form

Pit covers must remain on at all times

Date: 3-29-17
Time: 945-9
Initials: RLL



Sump Pits	Clean	Oil Sheen & Color	Comments
70k Room	سسب	h-	
6 Turbo Blower		Sump Water Diverted to Ash Pit	
7 Generator		Sump Water Diverted to Ash Pit	
5 Turbo Blower		Sump Water Diverted to Ash Pit	
7 Turbo Blower			
2300VAC Room			
8 Generator		Sump Water Diverted to Ash Pit	

If oil is found in sump pit contact KM to have the pit cleaned out.